## TYPE A/B CERTIFICATIONS USER GUIDE AGENCY (REGIONAL LAB)

Home 🔽 Previous 👻 My Pages 💌 T			•	0	Ċ
Switch Role	Verify Role.		Actions	Неір	Log off
C Brent Slade	onstruction Person Overview Reference Data				
ADMIN	per (Conjed from MATERIALLISED)				
CONSTRINSP_KS					
CONTRACTS_KS	?	✓ Construction			?
CONTRACTS_KS_NONC	· · · · · · · · · · · · · · · · · · ·	Change Order			
EXTERNALBIDDER		Contract Administration			•
		Contract Claims			
EXTERNALSUBPAYROLL		Contract Permits			
KDOT_CONTRACTS		Contract Prograss			
KDOT_LABORUSER					
✓MATERIALUSER_KS	× _				_
	·	Contract lime			
PROJIVAN_KS_AREA	2	Contract Vendor Assets			
PROJMAN KS CO		Contractor Evaluation			
PROJMAN_KS_DISTRICT		Meetings			
PROJMAN_KS_FHWA	×	Payment Estimate Accounting			•
Receive Sample at Destination Lab		Payment Estimate Approval Decisions			•
Receive Sample at Lab Unit	·	Payment Estimates			
Review Samples	$\nabla$				
Review Tests	▼				
✓ Person Overview				Save	• ?



0 marked for deletion 0 changed

Enter search criteria above to see results or Show first 10

✓ Reference Data	?
Administrative Offices	
Alternate Test Workflow	
Code Tables	$\mathbf{\nabla}$



## On this page: Materials Materials Worksheets Construction Person Overview Reference Data

My Pages - TEST ENVIRONMENT

Home 🔻

## PROJECT KDOT role for Materials User (Copied from MATERIALUSER)

✓ Materials	?	✓ Construction	?
Acceptance Actions		Change Order	
Action Relationships	•	Contract Administration	•
Daily Source Reports	•	Contract Claims	
Find Sample	•	Contract Permits	•
Mix Design	•	Contract Progress	•
Product Group Sample Reviewer Assignment	•	Contract Specific Authorities	
Sample Records < Click "Sample Records".	•	Contract Time	•
✓ Materials Worksheets	2	Contract Vendor Assets	
False Test Describe		Contractor Evaluation	
		Meetings	•
Maintain Test Queue		Payment Estimate Accounting	•
Receive Sample at Destination Lab	•	Payment Estimate Approval Decisions	-
Receive Sample at Lab Unit		Payment Estimates	-
Review Samples	•		
Review Tests	•		



0 marked for deletion 0 changed

Enter search criteria above to see results or Show first 10

✓ Reference Data	•
Administrative Offices	▼
Alternate Test Workflow	▼
Code Tables	· · · · · · · · · · · · · · · · · · ·



Home	TEST ENVIRONMENT	9. Click "Save".
Overview Add Sample Record	The Sample ID will automatically populate once you click "Save". LEAVE BLANK.	
General Sample Location Additional Information	Sample ID *	Sample Date 1. Select the date that the material was sampled.
Sources/Facilities Associations	Begin typing to search or press Enter     Administrative Office     G Begin typing to search or press Enter	Sample Type 3. Select "CTA" from the drop down.
2. Enter the material code for the material that was sampled.	Lab Control Number Lab Reference Number	Acceptance Method 4. Select "Cert" from the drop down. Authorized By
MUST be in a material set on a line item(s) on the contract that	Lot/Heat Number	Authorized Date
will be associated with this sample.	Seal Number	Revising Sample ID
	Sample Size Sample Size Units 5. Enter the Quantity represented to the sample. Represented Quantity	Link To Related Sample ID         Q Begin typing to search or press Enter         Linked Related Sample ID
	Represented Quantity Units Q Begin typing to search or press Enter 6. Enter the Unit	of Measure for the quantity.
	✓ Remarks     Type*   Remarks	•
		Q
7. OPTIO drop dowr	NAL: Select "Gen" from the information	IAL: Enter Remarks. Same as that was put in the Free Form Test in
	CMS. 5	Updated 07/22

INNE + Paeson + M Dverves Perd Sampe Mantan 1	Page - TEST ENVIRONMENT	Review Samples - Review Tests			Actorn	() tep	Logot
<ul> <li>Sample Record Summary</li> <li>Sample Record rickba/07</li> </ul>	20411032440		1 Click the component	action button			- 0
General Sample Location Associal Information Sources Associations Contract Tests	Sample (D *  Instand002004110002440  Material Code - Name		Remarks 0 Sample Data 0 Sample Data 0 Sample Data 0 Sample Data Sample Status Sample Status Sample Status CTA - CENTIFICATION TYPE A • Acceptance Method Acceptance Acceptance Acceptance Acceptance Acceptance	Actions Actions Actions Copy Tasks Autoscie Split Sampe Record Uniwitheritis trives Links Reports Sampe Laber Tesl Results Report Historical Reports Tesl Results Report			×

Home  Previous  My Pages  TEST ENVIRONMEN	іт					Actions	<b>?</b> Help	U Log off
Attachments Overview	There are unsaved changes.			×	(			
✓ Attachments For Sample Record				2.	Click "Save".	$\longrightarrow$	Save	• ?
Q       Type search criteria or press Enter       Image: Advanced         Select File       Image: Advanced         Cover sheet.pdf 472271 bytes	"Select File".	Select your co Cert that your	over sheet are enteri	for the Type A/ ng.	Έ 01	narked for deletion 0	changed	Expand All
> Filename		Historical Report	Size (kb)	Additional Roles Count				X
Cover sheet.pdf				0				
Description V		Attorney/Client Privilege 🔻						
Cover Sheet of Type A Cert.	(	a D						

Home   Home   Previous   My Pages   TEST ENVIRONMENT				Actions Help Log	у g off
Attachments Overview					
✓ Attachments For Sample Record				Save	?
Q Type search criteria or press Enter J Advanced Showing 1 of 1					
Scicul File				0 marked for deletion 0 changed Expa	and All
> Filename	Historical Report	Size (kb)	Additional Roles Count		
TestResultsReport.pdf	Yes		7 0		
Description 🔻	Attorney/Client Priv 1. C	lick the row a	ction button for y	our attachment.	>▼
Generated by Test Results Report on 06/16/2021 11:04:27	Q D			Actions	X
				Delete	
	2. CI	ick "Select R	oles".	Select Roles	



Home -	Select Roles		▼ (2) ×	U Log off
Attachmo	Q mat Advanced Showing 10 of 10			- 0
Q Type se	Select: All None	Role Description	2 selected	
Select File.	AREA	pay estimate user copied from contracts		
✓ Filenam	1. Select the role(s) you want to have access to the attachment.	SAMPLE ROLE for Estimation (DO NOT MODIFY)		Expand All
TestRes	ESTIMATION KS	KS ROLE for Design Stati		
Generated	ESTIMATION_KS_NONAGENCY	KS ROLE for Non Agency Estimation		
No routo fo	ESTIMATION_KS_READ ONLY	Read only role for Kansas Estimation		
NO TOWS IO	MATERIALUSER	SAMPLE ROLE for Material User (DO NOT MODIFY)		
	✓ MATERIALUSER_KS	KDOT role for Materials User (Copied from MATERIALUSER)		
	✓ MATERIALUSER_KS_SUPERVISOR	KS ROLE for Material User Supervisor		
	NONAGEESTIMATION	SAMPLE ROLE for Non Agency Estimation (DO NOT MODIFY)		
		2. Click "Add to Attachment".	attachment	

Home  Previous My Pages TEST ENVIRONMEN	,		Actions	<b>?</b> Help	U Log off
Attachments Overview	There are unsaved changes.	×			
2. Click "Previous".		1. Click "Save".	$\rightarrow$	Save	• ?

Q Type search criteria or press Enter 🖉 Advanced Showing 1 of 1

Select File ...

0 marked for deletion 0 changed Expand All

Historical Report	Size (kb)	Additional Roles Count	
Yes		7 0	
Attorney/Client Privilege 🔻			•
Role Description			×
KDOT role for Materials User (Copied from MATERIALUSER)			
KS ROLE for Material User Supervisor			×
	Historical Report Yes Attorney/Client Privilege  Attorney/Client Privilege Role Description KDOT role for Materials User (Copied from MATERIALUSER) KS ROLE for Material User Supervisor	Historical Report Size (kb) Yes Attorney/Client Privilege T Role Description KDOT role for Materials User (Copied from MATERIALUSER) KS ROLE for Material User Supervisor	Historical Report Size (kb) Additional Roles Count   Yes 7 0   Attorney/Client Privilege • •    Role Description  KDOT role for Materials User (Copied from MATERIALUSER)  KS ROLE for Material User Supervisor

	iction of Stockpile.		
Home	My Pages 👻 TEST ENVIRONMENT		Actions Heir
Overview Find Sample Maintai	1 Test Queue Receive at Destination Lab Receive at Lab Unit Review Samples Revie	w Tests	
Sample Record Summa	Sample Record slade20210616103000 - Successfully	Saved X	
✓ Sample Record: slade20	210616103000		Save
General	Sample Record: Test(s) may not be assigned to Sample Records without a Des	stination Lab association on the Associations tab.	
Sample Location	Sampled From	Reference	
Sources			
Associations	Sample Origin	Station	
Contract		Station Plus	
Tests	Geographic Area		
	tituda	Offset Distance	
"Additional Inform	hation".		
	Longitude	Offset Direction	
		•	
	Distance From Grade	Elevation	
		Comments	
	Distance From Grade Units		
	Sampled Ledge Name		
	✓ Location		
	Start Coordinate X	End Coordinate X	
	Start Coordinate Y	End Coordinate Y	
	Start Coordinate Z	End Coordinate Z	
	Start Location Method	End Location Method	
	•	-	
	Start Location Quality	End Location Quality	
	Start Location Quality Unit	End Location Quality Unit	
		•	
	Start Location Issue	End Location Issue	
		Q	
	Start Location Created By	End Location Created By	
	Begin typing to search of press Enter	Begin typing to search of press Enter	
	Start Location Created Date	End Location Created Date	
	Start Location Last Updated By	End Location Last Updated By	
	Legin typing to search of press Enter	Contraction of the second seco	
	Start Location Last Updated Date	End Location Last Updated Date	
	Start Location End Active Date	End Location End Active Date	

Home   Home	TEST ENVIRONMENT	Actions Het
Overview Find Sample Maintain Test Que	eue Receive at Destination Lab Receive at Lab Unit Review Samples R Save Complete	teview Tests
✓ Sample Record: slade202106161	103000	2. Click "Save".
General	Sample Record: Test(s) may not be assigned to Sample Records without a	Destination Lab association on the Associations tab.
Sample Location	Sampler ID - Name	Created By
Additional Information	Q Begin typing to search or press Enter	KDOTAD\slade
Sources	Witnessed By ID - Name	Created Date
Associations	Q Begin typing to search or press Enter	06/16/2021 10:30:00 AM
Contract	Requested By	Last Updated By
Tests	Q Begin typing to search or press Enter	KDOTAD\slade
ck "Sources"	Intended Use	Last Updated Date
		Q 06/16/2021 10:33:03 AM
	Mix Design Type	DWR Inspector
	Mix Design ID	DSR Inspector
	Q Begin typing to search or press Enter	
	Buy America	Limited Sample Access Last Modified By
	□ ← 1. Select the "Buy Ame	erica" check box.
	Buy USA Requirements	Limited Sample Access Last Modified Date
	•	
		Administrative Office Modified By
		Administrative Office Modified Date

Home	TEST ENVIRONMENT		Actions Help
Overview Find Sample Maintain Test Queue	e Receive at Destination Lab Receive at Lab Unit Review Samples Review	/ Tests	
Sample Record Summary	Save Complete	×	
✓ Sample Record: slade2021061610	3000		Save 🗸 ?
General	Sample Record: Test(s) may not be assigned to Sample Records without a Destin	nation Lab association on the Associations tab.	
Sample Location	✓ Primary Source/Facility		
Additional Information	Select Primary Source Select Primary Facility		
Sources	Source ID - Source Name	Facility ID - Facility Name	
Contract Click Tests	"Select Primary Source".	- Facility City	
	Source Type	Facility Type	
	Source Location Description	Facility Location Description	
	SMFMI Name Q Begin typing to search or press Enter V Additional Sources		
	Q Type search criteria or press Enter  Advanced Select Sources		0 marked for deletion 0 changed
	No rows found matching criteria.		
	Q     Type search criteria or press Enter     Image: Comparison of the search criteria of the search c		0 marked for deletion 0 changed
			•

✓ Sample Record: slade202100	316103000		Save 🗸 🖓
General Select Primary Source	e		×
Sample Loc Additional I Sources Association Contract	or press Enter Advanced e to see results or Show first 18	Either enter the Primary Source or click "Show first 10".	0 selected
Tests			Add to Sample Record
	Source Type	Facility Type	
	Source Location Description	Facility Location Description	
	SMFMI Name Q Begin typing to search or press Enter		
	Additional Sources      Q Type search criteria or press Enter     Advanced		
	Select Sources		0 marked for deletion 0 changed
	Additional Facilities      Q Type search criteria or press Enter     Advanced		
	Select Facilities No rows found matching criteria.		0 marked for deletion 0 changed

Home	Select Primary Source				× 2	U Log off
Overview F Sample F Samp General	Q CMC System Default Showing 6 of 6 1. Select the Primary S Source ID - Name	Source from the list.	Source City	Location Description	1 selected	• 0
Sample Loc	00014801 - CMC STEEL JACKSONVILLE	P - PRODUCER	JACKSONVILLE			
Sources	✓ 00014803 - CMC STEEL TENNESSEE	P - PRODUCER	KNOXVILLE			
Association	00015303 - CMC STEEL SOUTH CAROLINA	P - PRODUCER	CAYCE			
Contract	00015304 - CMC STEEL ARIZONA	P - PRODUCER	MESA			
Tests	00085501 - CMC STEEL	P - PRODUCER	SAYREVILLE			
	00015306 - CMC STEEL OKLAHOMA	P - PRODUCER	DURANT			
			2. Click "Add to Sar	mple Record".	Add to Sample Record	
	SMFMI Name Q Begin typing to search or press Enter ✓ Additional Sources					
	Q       Type search criteria or press Enter         Select Sources         No rows found matching criteria.         ✓       Additional Facilities	Advanced			0 marked for deletion 0 c	changed
	Q Type search criteria or press Enter	Advanced				

	Home	TEST ENVIRONMENT		Actions	<b>?</b> Help	<b>U</b> Log off
	Overview Find Sample Maintain Test Queue Sample Record Summary	Receive at Destination Lab Receive at Lab Unit Review Samples Review Tests There are unsaved changes.	×			
	<ul> <li>✓ Sample Record: rickba2022030403</li> </ul>	4518	1. Click "Save".	$\longrightarrow$	Save	- ?
	General	Sample Record: Test(s) may not be assigned to Sample Records without a Destination Lab association on the Associatio	uns tab.			
	Sample Location	✓ Primary Source/Facility				
	Additional Information	Select Primary Source Select Primary Facility				
	Sources	Source ID - Source Name	Facility ID - Facility Name			
	Associations	00014803 - CMC STEEL TENNESSEE				
	Contract	Source City	Facility City			
		KNOXVILLE				
2. Click	"Associations".	Source Type	Facility Type			
		P - PRODUCER				
		Source Location Description	Facility Location Description			
		SMFMI Name				
		Q Begin typing to search or press Enter				
		✓ Additional Sources				
		Q Type search criteria or press Enter				
		Select Sources		0 marked for dele	tion 0 c	hanged:
		No rows found matching criteria.				
		✓ Additional Facilities				
		Q     Type search criteria or press Enter   Advanced				

Home	TEST ENVIRONMENT		Actions Help Log off
Overview Find Sample Maintain Test Queue	Receive at Destination Lab Receive at Lab Unit Review Samples Review Tests		
Sample Record Summary	Save Complete	×	
✓ Sample Record: slade2021061610	3000		Save 🗸 ?
General	Sample Record: Test(s) may not be assigned to Sample Records without a Destination Lab association on the Associations tab.		
Sample Location			
Additional Information	Q     Type search criteria or press Enter     Image: Comparison of the press enter in the pr		
Sources			0 added 0 marked for deletion 0 changed
Associations			
Contract	No rows found matching criteria.		
Tests			

	Ann Annalds	
Sample Record Summary	Save Complete	×
✓ Sample Record: slade2021061610	3000	3. Click "Save".
General	Sample Record: Test(s) may not be assigned to Sample Records without a Destination Lab association on the Associations tab.	
Sample Location		
Additional Information	Q     Type search criteria or press Enter     Image: Advanced	
Sources		1 added 0 marked for dele
Associations	New	
Contract	Association Type* Association Value*	
Tests	Q Begin typing to search or press Enter	

Home   Previous   My Pages	TEST ENVIRONMENT		Actions Help Log off
Overview Find Sample Maintain Test Queue	Receive at Destination Lab Receive at Lab Unit Review Samples Review Tests		
Sample Record Summary	Save Complete	×	
✓ Sample Record: slade202106161030	00		Save 🔻 ?
General			
Sample Location	Q Type search criteria or press Enter 2 Advanced		
Additional Information	Select Contract Project Items Click "Select Contract Project Items".		0 marked for deletion 0 changed
Sources			
Associations	No rows found matching criteria.		
Contract			
Tests			

Home 💌	Select Contract Project Item Line Numbers	▼ (2) ×	U Log off
Overview F Sample F Samp General	Q Type search criteria or press Enter Select: All None Enter search criteria a contract number or click "Show first 10".	0 selected	- 0
Sample Loc Additional li Sources		Save	) changed
Associations Contract Tests	S No rows found matching criteria.		

Home 🔻	Select Contract Project Item Line Numbers						• 0 ×	U Log off
Overview F								
Sample F	Q 519022262-dew2	vanced Showing 9 of 9						
✓ Samp	Select: All None	1 Soloct th	o ling itom(s) from the list	1			1 selected	<b>- 0</b>
General	Contract		Project	]	Project Item Line Nbr	Material Set		
Sample Loc	519022262-dew2 - GRADING, SURFACING	G AND BRIDGE REPAIR	KA 4831-01-dev 2		96 - CONCRETE PAVEMENT (11" UNIFORM) (AE)	PCCP (NRDJ)		1 shares of
Sources	519022262-dew2 - GRADING, SURFACING	G AND BRIDGE REPAIR	KA 4831-01-dev 2		98 - CONCRETE PAVEMENT (11" UNIFORM) (AE)	Bridge Approach PCCP		J changed
Association	519022262-dew2 - GRADING, SURFACING	G AND BRIDGE REPAIR	KA 4831-01-de v2		98 - CONCRETE PAVEMENT (11" UNIFORM) (AE)	Conc Pvmt (11")(AE)(BR APP)		
Contract	519022262-dew2 - GRADING, SURFACING	G AND BRIDGE REPAIR	KA 4831-01-de <mark>v</mark> 2		58 - REINFORCING STEEL (GRADE 60) (EPOXY (	Rebar (GR 60)(Epoxy)		
Tests	519022262-dew2 - GRADING, SURFACING	G AND BRIDGE REPAIR	KA 4831-01-dew2		61 - BRIDGE REPAIR	014260 90 Set A		
	519022262-dew2 - GRADING, SURFACING	G AND BRIDGE REPAIR	KA 4831-01-dew2		61 - BRIDGE REPAIR	Bridge Repair		
	✓ 519022262-dew2 - GRADING, SURFACING	G AND BRIDGE REPAIR	KA 4831-01-dew2		78 - REINFORCING STEEL (GRADE 60) (EPOXY (	Rebar (GR 60)(Epoxy)		
	519022262-dew2 - GRADING, SURFACING	G AND BRIDGE REPAIR	KA 4831-01-dew2		81 - BRIDGE REPAIR	014260 90 Set A		
	519022262-dew2 - GRADING, SURFACING	G AND BRIDGE REPAIR	KA 4831-01-dew2		81 - BRIDGE REPAIR	Bridge Repair		
					2. Click "Save	"	Save	
						· /	ourc	

Home   Previous  My Pages	TEST ENVIRONMENT				Actions Help Log off
Overview Find Sample Maintain Test Que	eue Receive at Destination Lab Receive at Lab Unit Save successful	Review Samples Review Tests		×	
✓ Sample Record: slade20210616	103000				Save 🗸 ?
General Sample Location	Q Type search criteria or press Enter d Ad	Ivanced Showing 1 of 1			4. Click "Save".
Additional Information	Select Contract Project Items				0 marked for deletion 0 changed
Sources Associations	<b>√€ntract 1. E</b>	xpand the item.	Contract Project Item Material Sets		•
Contract Tests 5. Click "Tests".	Project           KA 4831-01-dew2           Fed St Proj Num           NHPP-A483(101) / U081-072 KA 4831-01           Work Location	ltem 025103 - REINFORC Proj Ln Num 78	Ma CING STEEL (GRADE 60) (EPOXY COAT Re Work Location Material Unit	terial Set Name bar (GR 60)(Epoxy) Remarks 0	
	Begin typing to search or press Enter		LBS.	vacantad Ausntifu	
	✓ Remarks	2. Enter the	Represented Quan	tity.	
	Туре*	Remark *			
	•				Q

Home	Previous	▼ My Pages ▼	TEST ENVIRONMENT										Actions	<b>e</b> Help	U Log off
Overview	Find Sample	Maintain Test Queue	Receive at Destination Lab	Receive at Lab Unit	Review Samples	Review 1	Tests								

Sample Record Summary		Save Complete		×	
✓ Sample Record: slade20210616103	000				Save 🗸 🖓
General	Material		Sampl	е Туре	
Sample Location	062016000 - EPOXY	COAT REBAR (CARBON) (GR60/GR420)	CRT -	MANUFACTURER'S CERTIFICATION	
Additional Information					
Sources	Q Type search crit	eria or press Enter 🥒 Advanced			
Associations		1. Cli	ck the action button.		0 marked for deletion 0 changed
Contract	Assign Tests 🔻				o maneer for deterior
Tests	No rows found ma	ctions 🗙			
		$\uparrow$			
2.	. Click "A	ssign Default Tests	•		



Home 

Home 

Previous 

My Pages 

TEST ENVIRONMENT



## Sample Record Test - 4. Click "Sample Record Test".

Agency View Summary

▼ Type A/B Certifications           3.	Click "Save" when finished entering all data.
Sample ID	Sample Type
slade20210616103000	СТА
Inspector ID	Lab Unit
	Wichita Regional Lab
Inspector Name	Lab Unit Description
	Wichita Regional Lab Unit
Source ID - Source Name	Material Code
10	062016000
Mix Plant Description	Material Code Description
CMC Steel	EPOXY COAT REBAR (CARBON) (GR60/GR420)
Mix Design	Quantity (Tons)
Contract	Project
519022262-dew2	U081-072 KA 4831-01
Line Number	Item Code
78	025103
	Item Code Description

REINFORCING STEEL (GRADE 60) (EPOXY COATED)





Home - Previous	My Pages      TEST ENVIRONME	NT			
Sample Record Test				Actions Help Log off	
Agency View Sur	mary	There are unsaved changes.		×	
✓ Type A/B Certific	ations			Save 🗸 🤉	Ĺ
Sample ID				Sample Type	ł
slade20210616103000				CTA	
Inspector ID				Lab Unit Wichita Regional Lab	
Inspector Name				Lab Unit Description Wichta Regional Lab Unit	
Source ID - Source Nam	2			- Material Code	
10				062016000	
Mix Plant Description				Material Code Description	
CMC Steel				EPOXY COAT REBAR (CARBON) (GR60/GR420)	
Mix Design				Quantity (Tons)	
Contract				Project	
519022262-dew2				U081-0/2 KA 4831-01	
78				025103	
				Item Code Description	
				REINFORCING STEEL (GRADE 60) (EPOXY COATED)	
New				6 added 70 marked for deletion 1 change	đ
48 #5 Bar	57160653	02	GERDAU AMERISTEEL TN.	ACC	
				•	
2,329 #5 Bar	57161625	02	GERDAU AMERISTEEL TN.	20A	
				×	
1,598 #6 Bar	56134093	02	GERDAU AMERISTEEL FL.	ACC	
				×	
46 #6 Bar	57151096	02	GERDAU AMERISTEEL TN.	ACC	
				×	
372 #6 Bar	57159664	02	GERDAU AMERISTEEL TN.	ACC	
				×	
564 #6 Bar	57160085	02	GERDAU AMERISTEEL TN.	ACC	
				X	

X

Remarks

Producer/Manufacturer/Mill/Brand

Qty.

4,948

Description

Total Weight in Lbs.

Heat/Lot/Batch/Bundle #

Home 👻 Previous 👻 My Pages	TEST ENVIRONMENT					Actions Help Log off	
Enter Test Results Maintain Test Queue Re	eview Samples Review Test	ts Sample Record					
Sample Record Test Summary							
Sample Record ID: slade20210616	6103000					Save 🖵 ?	
Test Number: 1.0 Test Method - Description: Ty	ype A Certification - Type A Ce	ert Authorization				7	
General	✓ Test Information						
Testers	Test Status			Remarks	ſ		
Reference Specifications	05 - Test Assigned			0	2 Click "S	Sovo"	
Retests	Priority			Planned Test Start Date	Z. CIICK C	save.	
				<b>m</b>			
	Default Test			Test Start Date			
	Yes			06/16/2021			
	Required Test			Estimated Completion Date			
	NO						
	Due Date			Actual Completion Date			
	Comple Information						
	Sample Type	uon		Contract ID			
	CTA - CERTIFICATION 1	TYPE A		519022262-dew2			
	Lab Unit			Source			
	Wichita Regional Lab - V	Vichita Regional Lab Unit		00000303 - CMC Steel			
	Lab Reference Number	r.		Sample Date			
		4 Calact the expression test	recult	7			
	Test Result Value	1. Select the appropriate test	result	Sample Record Remarks			
	$\leftarrow$	– from the drop down. Options a	are	1			
		Pass Fail PAAA		Counts Toward MAA			
				No			
	✓ Sample Record F	Remarks					
	Туре		Remark				
	GEN - General Remarks Q Tag			agged B-1056154 Order No 40057672Black Bar Accepted on CMTR's on file at Wichita Lab			
	✓ Additional Test In	nformation					
	Retest Test			Reportable			
	No			Yes			
	Number of Retests			Updateable			
	Retest Requested						
	No						
	Test Requeued						
	No						
	✓ Remarks	lest Requeued					
	Туре *		Remark *				
	•					Q	