RIP RAP GRADATION USER GUIDE (DISTRICT)

Home Previous V My Pages V).		Actions H	P (U og off
Switch Role						_
G Brent Slade	construction Person Overview Reference Data					
ADMIN	ser (Copied from MATERIALUSER)					
CONSTRINSP_KS						
CONTRACTS_KS		?	✓ Construction			?
CONTRACTS_KS_NONC			Change Order			•
EXTERNALBIDDER			Contract Administration			-
		-	Contract Claims			-
EXTERNALSODPATROLL			Contract Permits			
		•	Contract Progress			
✓MATERIALUSER_KS		•	Contract Specific Authorities			•
000			Contract Time			•
PROJMAN_KS_AREA			Contract Vendor Assets			•
PROJMAN_KS_BUREAU		9	Contractor Evaluation			-
PROJMAN_KS_CO		•	Maatings			-
PROJMAN_KS_DISTRICT			weenings			
PROJMAN_KS_FHWA			Payment Estimate Accounting			
Peceive Sample at Lab Unit		-	Payment Estimate Approval Decisions			
Receive Sample at Lab Onit		_	Payment Estimates			
Review Samples						
Review Tests		•				
✓ Person Overview				Sa	ve 🔻	?
	Qualifications User Refer	ence Employee				
Q Type search criteria or press Enter Advance	No Filter No Filter No Filter	ilter 🔹				
				0 marked for delet	ion 0 ch	hanged
				o manea for dele		
Enter search criteria above to see results or Show f	rst 10					
✓ Reference Data						?

✓ Reference Data Administrative Offices Alternate Test Workflow

Code Tables

Home Previous My Pages TEST ENVIRONMENT

Actions Help Log off

On this page: Materials Materials Worksheets Construction Person Overview Reference Data

PROJECT KDOT role for Materials User (Copied from MATERIALUSER)

✓ Materials	?	✓ Construction	?
Acceptance Actions		Change Order	
Action Relationships	•	Contract Administration	•
Daily Source Reports	•	Contract Claims	•
Find Sample		Contract Permits	•
Mix Design	•	Contract Progress	•
Product Group Sample Reviewer Assignment		Contract Specific Authorities	•
sample Records <click "sample="" on="" records".<="" td=""><td>•</td><td>Contract Time</td><td>•</td></click>	•	Contract Time	•
✓ Materials Worksheets	2	Contract Vendor Assets	
Enter Table Describe		Contractor Evaluation	
Enter rest Results	_	Meetings	
		Payment Estimate Accounting	
Receive Sample at Destination Lab		Payment Estimate Approval Decisions	
Receive Sample at Lab Unit		Payment Estimates	
Review Samples			
Review Tests			

✓ Person Overview							
		Qualifications	;	User		Reference Er	nployee
Q Type search criteria or press Enter	Advanced	No Filter	•	No Filter	•	No Filter	•

0 marked for deletion 0 changed

Enter search criteria above to see results or Show first 10

✓ Reference Data	?
Administrative Offices	•
Alternate Test Workflow	▼
Code Tables	•

Home Previous My Pages TEST ENVIRONMENT		Ac	ions Help	U Log off
Sample Record Overview				
✓ Sample Record Overview	1. Click on the component row a	ction button.		- ?
		Actions		×
Q Type search criteria or press Enter System Default	2. Click "Add".	► Add		
		0 marke	d for deletion	0 changed

Enter search criteria above to see results or Show first 10

Home Previous My Pages	TEST ENVIRONMENT			Actions Help Log off	
Overview					
Add Sample Record				-	
✓ Add Sample Record			7. Click "Save".		
General Sample Location	Sample ID *	2. Enter the material code for the material	sample Date 1. Enter the d	ate the material was	
Addit/Onal Information Sources/Facilities Associations	Material Code - Name Q Begin typing to search or press Enter Administrative Office	Material code must exist	Sample Status		
8. Click "Sample Location".	Q Begin typing to search or press Enter Lab Control Number	will be assigning the test to.	Acceptance Method Acceptance Method 4. Select "ACCP"	from the drop down.	
	Lab Reference Number		Authorized By		
	Lot/Heat Number		Authorized Date		
	Seal Number		Revised By		
	Sample Size		Link To Related Sample ID Q Begin typing to search or press Enter		
	Sample Size Units		Linked Related Sample ID		
	Represented Quantity	er the quantity being represe	ented by the test.		
	Represented Quantity Units Q Begin typing to search or press Enter	6. Enter the Units for the	Represented Quantity above.		
	✓ Remarks	Barr 1.0			
	iype *	Remark *			
	•			Q	

Home Previous My Pages	TEST ENVIRONMENT	Actions Help I
Overview Find Sample Maintain Test Queue	Receive at Destination Lab Receive at Lab Unit Review Samples Review Tests	
Sample Record Summary	Sample Record slade20210706070822 - Successfully Saved	
✓ Sample Record: slade20210706070	822	3. Click "Save".
General	Sample Record: Test(s) may not be assigned to Sample Records without a Destination Lab association on the Associat	ions tab.
Sample Location	Sampled From	e menteniel over energie el freme
Additional Information	1. Enter where the	e material was sampled from.
Sources	Sample Origin	Station
Associations	9	
Tests	Geographic Area 2 Select the appropriate deporta	phic area
	Latitude Ifrom the drop down.	
Click "Additional Information".	gitude	Offset Direction
		•
	Distance From Grade	Elevation
	Distance From Grade Units	Comments
	•	
	Sampled Ledge Name	
	•	
	✓ Location	
	Start Coordinate X	End Coordinate X
	Start Coordinate Y	
	Start Coordinate Z	End Coordinate Z
	Start Location Method	End Location Method
		•
	Start Location Quality	End Location Quality
		•
	Start Location Quality Unit	End Location Quality Unit
	•	•
	Start Location Issue	End Location Issue
	0	٩
	Start Location Created By	End Location Created By
	Q Begin typing to search or press Enter	Q Begin typing to search or press Enter
	Start Location Created Date	End Location Created Date
	(m)	m
	Start Location Last Updated By	End Location Last Updated By
	Q Begin typing to search or press Enter	Q Begin typing to search or press Enter
	Start Location Last Updated Date	End Location Last Updated Date
	Start Location End Active Date	End Location End Active Date

Home	ST ENVIRONMENT	Actions	P Help
Overview Find Sample Maintain Test Queue Rece Sample Record Summary	ceive at Destination Lab Receive at Lab Unit Review Samples Review Tests Save Complete	×	
✓ Sample Record: slade20210706070822		3. Click "Save".	Save
General	mple Record: Test(s) may not be assigned to Sample Records without a Destination Lab association on the Association	ns tab.	
Sample Location Sample Additional Information Q	Begin typing to search or press Enter	Created By ed the material.	
Sources With Associations Q	nessed By ID - Name Begin typing to search or press Enter	Created Date 07/06/2021 7:08:22 AM	
Contlact Tests ick "Sources".	2. Select who requested the test fr the drop down.	Last Updated By TADIslade Last Updated Date 07/06/2021 7:11:13 AM	
		DWR Inspector	
	Design Type	DSR Inspector	
Q	Begin typing to search or press Enter v America	Limited Sample Access Last Modified By	
Buy I	y USA Requirements	Limited Sample Access Last Modified Date	
	•	Administrative Office Modified By	
		Administrative Office Modified Date	



Actions Help Log off

Overview Find Sample Maintain Test Queue Receive at Destination Lab Receive at Lab Unit Review Samples Review Tests

Sample Record Summary	Save Complete	×					
✓ Sample Record: slade202107060	070822		Save 🔻 ?				
General	Sample Record: Test(s) may not be assigned to Sample Records without a Des	tination Lab association on the Associations tab.					
Sample Location	✓ Primary Source/Facility						
Additional Information	Select Primary Source Select Primary Facility						
Sources	Source ID - Source Name	Facility ID - Facility Name					
Associations		-					
Contract	Select Primary Source"	Facility City					
Tests							
	Source Type	Facility Type					
	Source Location Description	Facility Location Description					
	SMFMI Name						
	Q Begin typing to search or press Enter						
	✓ Additional Sources	✓ Additional Sources					
	Q Type search criteria or press Enter 🥒 Advanced						
	Select Sources		0 marked for deletion 0 changed				
	No rows found matching criteria.						
	 Additional Facilities 						

Q Type search criteria or press Enter 🥒 Advanced

Home Select Primary Source			▼ P × Log off
Overview F Sample Image: Constraint of the second seco	Enter Advanced results or Show first 10	Either enter the source for the material or click "Show first 10".	0 selected
Additional I Sources	Source ID - Source Name	Facility ID - Facility Name	Add to Sample Record
Contract Tests	- Source City	- Facility City	
	Source Type	Facility Type	
	Source Location Description	Facility Location Description	
	SMFMI Name Q Begin typing to search or press Enter		
	Additional Sources Q Type search criteria or press Enter Advanced		
	Select Sources		0 marked for deletion 0 changed
	Additional Facilities		

Home 🔻	Select Primary Source				▼ P × Log off
overview F Sample F	Q harshman Advanced Showing 7 of 7	Select the source	e for the material.		- 0
General	Source ID - Name	Source Type	Source City	Location Description	1 selected
Sample Loc	00800940 - HARSHMAN CONSTRUCTION (VANMETER QUARRY)(WABUNS	QL - LIMESTONE QUARRY	ESKRIDGE	SW 1/4 S32T14SR12E	
Additional I Sources	00800111 - HARSHMAN CONST CO (PRINGLE QUARRY) (WOODSON CO)	QL - LIMESTONE QUARRY	YATES CITER	W 1/2 S19T26SR16E	
Association	00801503 - HARSHMAN CONSTRUCTION (PAXSON QUARRY)(COFFEY CO	QL - LIMESTONE QUARRY	BURLINGTON	NW 1/4 S33T21SR14E	
Contract	00801507 - HARSHMAN CONSTRUCTION (HILLTOP QU)(GREENWOOD CC	QL - LIMESTONE QUARRY	GRIDLEY	NE 1/2 S07T23SR13E	
Tests	✓ 00801512 - HARSHMAN CONSTRUCTION(WAVERLY QUARRY)(OSAGE CC	QL - LIMESTONE QUARRY	MELVERN	NW 1/4 & SW 1/4 S25T18SR16E	
	00801515 - HARSHMAN CONSTRUCTION CO. (FLOYD QU)(CHAUTAUQUA	QL - LIMESTONE QUARRY	SEDAN	NE 1/4 S20T34SR11E	
	00801519 - HARSHMAN CONST (MILLER QUARRY) (ANDERSON CO)	QL - LIMESTONE QUARRY	RICHMOND	NW 1/4 S07T20SR19E	
			2. Click "Add to S	Sample Record".	id to Sample Record
	 Q Begin typing to search or press Enter Additional Sources 				
	Q Type search criteria or press Enter	dvanced			0 marked for deletion 0 channed
	Select Sources				o marked for deletion pointinged
	No rows found matching criteria.				
	✓ Additional Facilities				
	Q Type search criteria or press Enter	dvanced			



Actions Help Log off

Overview Find Sample Maintain Test Queue Receive at Destination Lab Receive at Lab Unit Review Samples Review Tests

Sample Record Summary	There are unsaved changes.	×	
✓ Sample Record: slade202107060708	822	1. Click "Save".	
General	Sample Record: Test(s) may not be assigned to Sample Records without a Destination Lab asso	vciation on the Associations tab.	
Sample Location	✓ Primary Source/Facility		
Additional Information	Select Primary Source Select Primary Facility		
Sources	Source ID - Source Name	Facility ID - Facility Name	
Associations	00801512 - HARSHMAN CONSTRUCTION(WAVERLY QUARRY)(OSAGE CO)		
Contract	2. Click "Select Primary Facility".	Facility City	
Tests	MELVERN		
	Source Type	Facility Type	
	QL - LIMESTONE QUARRY		
	Source Location Description	Facility Location Description	
	NW 1/4 & SW 1/4 S25T18SR16E		
	SMFMI Name Q Begin typing to search or press Enter		
	✓ Additional Sources		
	Q Type search criteria or press Enter		
	Select Sources		0 marked for deletion 0 changed
	No rows found matching criteria.		
	✓ Additional Facilities		

Home Select Primary Facility			► P U
Overview F Sample I Sample General Sample Loc	press Enter Advanced Either ente	r the facility or click "Show first 10".	0 selected
Additional I			Add to Sample Record
Sources	Source ID - Source Name	Facility ID - Facility Name	
Associations	00801512 - HARSHMAN CONSTRUCTION(WAVERLY QUARRY)(OSAGE CO)	•	
Tests	Source City	Facility City	
	MELVERN		
	Source Type	Facility Type	
	Source Location Description NW 1/4 & SW 1/4 S25T18SR16E	Facility Location Description	
	Begin typing to search or press Enter		
	✓ Additional Sources		
	Type search criteria or press Enter Advanced Select Sources No rows found matching criteria.		0 marked for deletion 0 changed
	✓ Additional Facilities		
	Q Type search criteria or press Enter d Advanced		

Home	Select Primary Facility					× 0 ×	U Log off
Overview F Sample F Samp General Sample Loo Additional I Sources	Type search criteria or press Facility ID - Name O0801512 - KERFORD	Enter Advanced Showing 1 of 1	1. Select th Facility Type	e "Facility". Facility City	Location Description NW 1/4 & SW 1/4 S25T18SR16E	1 selected	• 0
Association				2. Click "/	Add to Sample Record".	Add to Sample Record	
Tests		Source City MELVERN		٢	aciinty City		
		Source Type QL - LIMESTONE QUARRY		F	acility Type		
		Source Location Description NW 1/4 & SW 1/4 S25T18SR16E		F	acility Location Description		
		SMFMI Name Q Begin typing to search or press Enter					
		✓ Additional Sources					
		Q Type search criteria or press Enter	Advanced			0 marked for deletion 0 c	changed
		No rows found matching criteria.					
		✓ Additional Facilities					

	Home Home Home	TEST ENVIRONMEN	Π			Actions	? Help	U Log off
(Overview Find Sample Maintain Test Queue	Receive at Destinatio	n Lab Receive at Lab Unit Review Samples Review Tests					
	Sample Record Summary		There are unsaved changes.		×			
	✓ Sample Record: slade202107060708	322			1. Click "Save".	\rightarrow	Save	• ?
	General	Sample Record: Tes	t(s) may not be assigned to Sample Records without a Destination Lab association on t	the Associatior	is tab.			
	Sample Location	✓ Primary Sour	ce/Facility					
	Additional Information	Select Primary Sou	rce Select Primary Facility					
	Sources	Source ID - Source	Name		Facility ID - Facility Name			
	Associations	00801512 - HARSHI	IAN CONSTRUCTION(WAVERLY QUARRY)(OSAGE CO)		00801512 - KERFORD LIMESTONE (KRFD)			
	Contract	Source City			Facility City			
	Tests	MELVERN						
		Source Type			Facility Type			
2. Click "	Associations".	QL - LIMESTONE QI	JARRY					
		Source Location De	scription		Facility Location Description			
		NW 1/4 & SW 1/4 S2	5T18SR16E		NW 1/4 & SW 1/4 S25T18SR16E			
		SMFMI Name						
		Q Begin typing to	search or press Enter					
		✓ Additional So	urces					
		Q Type search crit	eria or press Enter 🥒 Advanced					
		Select Sources				0 marked for dele	etion 0	changed
		No rows found match	ing criteria.					
		✓ Additional Fa	cilities					

Q Type search criteria or press Enter 🥒 Advanced

Home V Previous V My Pages V TEST ENVIRONMENT					
Overview Find Sample Maintain Test Queue	Receive at Destination Lab Receive at Lab Unit Review Samples Review Tests				
Sample Record Summary	Save Complete X				
✓ Sample Record: slade20210706070	822		Save	7 ?	
General	Sample Record: Test(s) may not be assigned to Sample Records without a Destination Lab association on the Associations tab.				
Sample Location					
Additional Information	Q Type search criteria or press Enter Image: Advanced				
Sources	Click "Now"	0 added 0 marked for dele	etion 0 cl	hanged	
Associations				-	
Contract	No rows found matching criteria.				
Tests					



Home Previous My Pages	TEST ENVIRONMENT	Actions Help Log off
Overview Find Sample Maintain Test Queue	Receive at Destination Lab Receive at Lab Unit Review Samples Review Tests	
Sample Record Summary	Save Complete X	
✓ Sample Record: slade202107060708	822	Save 🔻 ?
General		
Sample Location	Q Type search criteria or press Enter Image: Advanced	
Additional Information	Select Contract Project Items Click "Select Contract Project Items".	0 marked for deletion 0 changed
Sources		
Associations	No rows found matching criteria.	
Contract		
Tests		



Home 🔽				•	<u>)</u>
	Select Contract Project Item Line Numbers			2	Log off
Overview F					
Sample F	Annual Hannah	1. Select your contract/line item.			
✓ Samp	Q Type search criteria or press Enter Advanced Showing 1 of 1 Select: All None			1 selected	- 0
General	Contract	Project	Project Item Line Nbr	Material Set	
Sample Loc Additional I	✓ 519022262-dew2 - GRADING, SURFACING AND BRIDGE REPAIR	KA 4831-01-dew2	93 - SLOPE PROTECTION (AGGREGATE)	SLOPE PROTECTION (AGGREGATE)) channed
Sources					J unangea
Association			2. Click "Save".	Save	
Contract					
Tests					

Home Previous My Pages	TEST ENVIRONMENT	w Samples Review Tests			Actions Help Log of
Sample Record Summary	Save successful			×	
✓ Sample Record: slade20210706070	822			3. Click "Save".	Save V ?
General Sample Location Additional Information Sources Associations Contract Tests L. Click "Tests".	Q Type search criteria or press Enter Advance Select Contract Project Items 1. E V Centract 519022262-dew2 Project KA 4831-01-dew2 Fed St Proj Num NHPP-A483(101) / U081-072 KA 4831-01 Work Location Q Begin typing to search or press Enter	d Showing 1 of 1 Expand the row. Con 1 Item 070970 - SLOPE PROTECTION (A Proj Ln Num 93	tract Project Item Material Sets GGREGATE) SLOP Work Location Material Unit TON	ial Set Name E PROTECTION (AGGREGATE) Remarks 0	0 marked for deletion 0 changed
	Represented Quantity	2. Enter the quantit	Satisfied Repres	ented Quantity ed to the line.	Q

Home 💌 Previous 💌 My Pages	TEST ENVIRONMENT				Actions	? Help	U Log off
Overview Find Sample Maintain Test Queue	Receive at Destination Lab Rec	eive at Lab Unit Review Samples F	Review Tests				
Sample Record Summary	Save Com	plete	x				
✓ Sample Record: slade20210706070)822					Save	• ?
General	Material		Sample Type				
Sample Location	AGGRIP_0.75 ton - Aggregate for	Rip Rap 3/4 ton	ACC - Acceptance				
Additional Information							
Sources	Q Type search criteria or press	Enter 🥒 Advanced					
Associations					0 meeting differential		
Contract	Assign Tests	1	. Click the action button next to "Assign	Tests".	U marked for del	Buon U C	nanged
Tests	No rows found ma	×					
2.	Click "Assign Default	Default Tests".					



Home P Sample Record Tes	My Pages TEST ENVIRONMENT 3. Click "Sample Record Test".	Actions G	り g off
Agency View	Summary Rap Gradation	2 Click "Save"	0
Sample ID		Sample Type	
Inspector ID		Lab Unit	
Inspector Name		Lab Unit Description	
Mix Plant		Material Code	
Mix Plant Descrip	ion	Material Code Description	
Mix Design		Quantity (Tons)	
Contract		Project	
Line Number		Item Code	
		Item Code Description	
New		0 added 0 0 ch	anged
			•
Stone for Rip Ra Gradations (Cun	ip nulative % Retained)		
4 7000			
4 1015			
3 Tons			
2 Tons			
1 1/2 Tons	\leftarrow		
1 Ton	\leftarrow		
3/4 Ton	\leftarrow		
1/2 Ton	4	1. Enter your gradation data.	
1/4 Ton			
200 LDS			
200 Lbs			
100 Lbs			
75 Lbs			
5 Lbs	\mathbf{k}		

Home	TEST ENVIRONMENT			Actions Help Log off
Enter Test Results Maintain Test Queue	Review Samples Review Tests	Sample Record		
Sample Record Test Summa	iry			
✓ Sample Record ID: slade2021	0706070822		2. Click "Save".	Save - ?
Test Number: 1.0 Test Method - Description	on: Rip Rap Gradation - Gradation Tes	ting for Rip Rap		
General	Test Information			
Testers	Test Status		Remarks	
Reference Specifications	05 - Test Assigned		0	
Retests	Priority		Planned Test Start Date	
			m	
	Default Test		Test Start Date	
	Yes		07/06/2021	
	Required Test		Estimated Completion Date	
	No		m	
	Due Date		Actual Completion Date	
				
	✓ Sample Information	ı		
	Sample Type		Contract ID	
	ACC - Acceptance		519022262-dew2	
	Lab Unit		Source	
	District 1 Materials Lab - Dis	strict 1 Materials Lab Unit	00801512 - HARSHMAN CONSTRUCTION(WAVERLY QUARRY)(OSAGE CO)	
	Lab Reference Number		Sample Date	
		1. Select the appropriate test		
	Test Result Value	result from the drop down.	Sample Record Remarks	
	\leftarrow		0	
		Options are PASS, PAAA, FAIL,	Counts Toward MAA	
		COMP.	Yes	
	Sample Record Por	marke		
	V Sample Record Rel	Bamark		
	туре	Reliaik		
	Additional Test Info	rmation		
	Additional rest mio	inauon	Provide black	
	Retest lest		Vee	
	NU		105	
	Number of Retests		Updateable	
			Yes	
	Retest Requested			
	No			
	Test Requeued			
	No			
	✓ Remarks			
	Type *	Remark *		
	-			Q